



## Technical Bulletin

February 16, 2007

### BROADCAST ELECTRONICS CUSTOMER SERVICE

Recipients of this Technical Update receive notices from BE Customer Service on product updates and other information for users of BE equipment.

### BE SUPPORT

#### Radio Transmitters & RF Products

Tel: 217.224.9617

[rfservice@bdcast.com](mailto:rfservice@bdcast.com)

### CRITICAL SOFTWARE UPDATE FOR ASI 10 NOW AVAILABLE

#### Version 2.3.3p1

Broadcast Electronics has released **new ASI 10 software**.



On February 16th, 2007, **version 2.3.3p1** was released. The software update is available from the Broadcast Electronics Customer Service website in the Registered User Login section on:

<http://www.bdcast.com/support/>

Please note there are two sets of instructions included in the downloaded zipped file. **It is imperative to follow the included instructions as some settings will be restored to factory default upon successful completion of the software upgrade.** The "Downloading Software Upgrade Files from the BE Website and Burning to CD Application Guide" includes a detailed step by step process to create the 2.3.3p1 upgrade CD from the downloaded file using a CD-RW drive. The "ASI 10 Software Upgrade, Upgrading to v2.3.3p1 Application Guide" will provide upgrade assistance after the upgrade CD has been created.

If you prefer to have a CD with Version 2.3.3p1 mailed to you, contact the RF Service department by phone on 217.224.9617 or e-mail [rfservice@bdcast.com](mailto:rfservice@bdcast.com) and request kit 979-6025-233P1.

Major change to the ASI 10 software from version 2.3.3 to version 2.3.3p1:

DUC II driver updated to eliminate non operational errors caused by erroneous PCI motherboard interrupts.

Thank you for choosing Broadcast Electronics!

[www.bdcast.com](http://www.bdcast.com)

Broadcast Electronics, Inc. [Legal notices](#)