



## Technical Bulletin

December 3, 2018

### BROADCAST ELECTRONICS TECHNICAL SERVICES

Recipients of this Technical Update receive notices from BE Technical Services on product updates and other information for users of BE equipment.

**BE SUPPORT**  
**AudioVAULT/Digital Studio Products**  
Tel: 217.224.4700  
[service@bdcast.com](mailto:service@bdcast.com)



### New HD Radio Gen4 Importer version 5.1.2 release for the IDi 50 Importers

On December 3, 2018, Broadcast Electronics has released XPERI Importer version 5.1.2 for IDi 50 Importers. The updated software suite is immediately available as a download only.

Please contact the Studio Technical Services department by phone at 217.224.4700 or e-mail [service@bdcast.com](mailto:service@bdcast.com) and request the download link for the Importer version 5.1.2 installation package.

Importer v5.1.2 software is available per request from the Studio Technical Services Department.

#### Summary of Importer version 5.1.2

1. New Gen4 Imp-Exp Architecture
2. Windows 7 and 10 Support
3. New Java based Control Panel for easy operation
4. 42 Pre-Defined Configurations and Services
5. JMSAC for Artist Experience built-in
6. Audio Client Improvements
7. Built in Log Panel
8. Backup and Restore capability
9. Robust PSD filtering
10. Remote UI

#### Fixes for Importer version 5.1.2

1. If connection to Exporter is lost then recovers the Control Panel automatically reconnects.
2. Allows for TRE PAD ports in the 4000 range

#### Documentation to assist in the Installation

1. [597-2010-008](#) – Software Upgrade Application Guide

**Windows XP no longer supported**

Thank you for choosing Broadcast Electronics!  
[www.bdcast.com](http://www.bdcast.com)

Broadcast Electronics [Legal notices](#)